


### 9104D10 D10"H10"L4



We are dedicated to providing the finest quality crystal chandelier for our customers. Our master craftsmen and designer pride themselves on their attention to detail. prompt, efficient service is our priority. Enclosed, are detailed instructions on how to properly. install your chandelier. Please read all instructions carefully and thoroughly. If you have any questions please fell free to call our toll free CHANDELIER HOTLINE AT:

1-888-388-3390  $^{(I)}_{\text{@L}}$   $^{(I)}_{\text{C}}$   $^{(I)}_{\text{US}}$ 

## WARNING!!!

### CONTENTS ARE FRAGILE HANDLE WITH CARE

and installation. excersise extreme caution during unpacking of this chandelier are very delicate. Please The metal frame and crystal components

## WARNING!!

After passing the main electrical wire through the 10mm pipe and connecting the pipe to the main body top connector, place all remaining pieces as shown in numerical order and in the orientation depicted. Refer to the parts list to avoid confusion between parts. The part numbers coincide.


- 1. Rated 110-1307/60Hz, bulb 407 maximum 2. Care should be taken to avoid demage to the surface of lighting and wire, wearing gloves is recommended when installing.
- and double colored (or bare copper) wire to ground wire.

  4. Never install lighting on demp ceiling, the room should be dry and well ventilated. 3. Connect black or red wire of the lighting to live wire and white or blue wire to neutral wire
- 5. Keep lighting eway from soid, alkali and other corrosive chemical or gas, clean the lighting with clean soft cloth only.
- 6. Installation must be carried out by qualified electricism only.
  7. Disconnect the power before installing cleaning and replacing lighting.
- 8. Never cover the lighting when power is connected.
- Firmness must be secured when installing ceiling tube, chain pipe and other connecting parts.
- 10. Care should be taken to avoid demage when installing glass parts.
  11. All electrical components must be installed by a licensed electrician and in accordance with the National Electrical Code and the appropriate local electrical codes. Make sure that the electrical supply to the chandellier is turned off at the main fuse or circuit breaker

before doing any installation

9104 D10"H10"L4

# Crystal Dressing Instructions





4 strings 16 strings 4 strings 4 strings 4 strings 4 strings 1 strings	Ä	Ħ	D	ဂ	В	>	No
	1 strings	4 strings	4 strings	4 strings		4 strings	Quantity




**(5**)

9104 D10"H10"L4

### **Crystal Dressing** Diagram

When dressing the chandelier with the crystals please remember to wear either rubber or cotton gloves. So as to prevent any

bemage or smudging on the crystals.



Connect both ends of E with C

8

9104 D10"H10"L4

## CANOPY PARTS LIST

ZA: Existing Electrical Box (not supplied) ZB:Crossbar



ZC:Crossbar Screws x 2(not supplied)



ZD:Canopy lock



ZE:Canopy

ZF:Metal Ring



ZG:Chain

ZH:Ground Wire



ZJ:Electric Main

ZI:Canopy Loop




ZK: Junction Caps



(3)

### 9104 D10"H10"L4

# CANOPY INSTALLATION DIAGRAM



9104 D10"H10"L4

## Frame Assembly Instructions

Please read all instructions carefully. Before you proceed to install, make sure that the power supply is tamed off and off until installation is complete. Please note that each part has been assigned a letter. Please proceed in alphabetical order.

- 1. Install (Cast Canopy)01 to the electic Box and wire properly.
- 2 .using (Ground Screw)03, Connect the Loose (chain Connector)02 on the (All thread)08.
- 3 . Dressing Crystal using Diagram provided

The end!

8

## Fram Parts List



18-Nut

14-All thread



19-Bottom Cover

15-Cast Arm

20-All thread

16-All thread

Ш

17-Spring Seat

21-Cast Bottom Finial

9104 D10"H10"L4

# CANOPY INSTALLATION INSTRUCTIONS

off until installation is complete. Please note that each part has install, make sure that the power supply is tamed off and been assigned a letter.Please proceed in alphabetical order. Please read all instructions carefully. Before you proceed to

ZA. Junction Box (not supplied)

ZB. Crossbar

ZC. Crossbar Screws

ZD. Canopy Loop

ZE. Canopy

ZF. Metal Ring

ZG. Chain

ZH. Ground Wire

ZI. Canopy loop

ZK. Junction Caps ZJ. Electric loop

1. Attach the Crossbar (ZB) to the Junction Box (ZA) using the two already be in your box. crossbar screws (ZC) which are not supplied and should

2. Slide the Metal Ring (ZF) back up over the canopy (ZE) pass the canopy loop(ZD)through canopy(ZE), connect with the threaded pipe underside of the crossbar.

3. Pass the electric loop(ZJ) and ground wire (ZH) through the chain(ZG), junction box(ZA) where you can make the appropriate connections crossbar(ZB)until the end of the electric Loop(ZJ) reaches the the Metal Ring(ZF), the canopy (ZE), the canopy loop(ZD) and the

4. Be sure when connecting the

wire use electrician approved junction caps(ZK)

6. Raise the canopy (ZE). 5. Stow the excess wire in the junction box (ZA).

7. Metal Ring(ZF), attach canopy(ZE) to ceiling, slide Metal Ring(ZF) over canopy loop(ZD) and hold the canopy(ZE).

### 9104 D10"H10"L4 Frame Assembly Diagram 10 11 12 13 13 6 2 9 9 9 9 2 22024 8 02-chain Connector 01-Cast Canopy © 3-Ground Screw 04-Set Screw Fram Parts List 05-Cast Bobeche 08-All thread 06-Mid Column 07-Top Cover 8 10-Sleeve cover 09-Cost Column 13-Cast Socket © 12-Washer 11-Socket